

VEHICLE INSPECTION REPORT

LG65ZLU

Skoda Fabia 1.4 TDI SE 5dr DSG

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	30/09/2015
Year	2015
Mileage	89,176 Miles Warranted
Fuel Type	Diesel
Colour	BLACK
VIN	TMBFJ6NJ0FZ052728

Body Style	Hatchback
Keys	3
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	16/11/2020

Last service miles	47,042
MOT Due	15/10/2026
Gearbox	SEMI AUTO
Gears	7
Doors	5

£65 ADDITIONAL FEE

Last service 16/11/2020 at 47,042 miles- 3 main dealer services. Print

Tyres




NSF	BUDGET	3.0mm
NSR	INVOVIC	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Dented
Between 10mm + 30mm

No Image


4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Sill ns
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Wheel nsr
Scratched
Up To 50mm

14: Bumper Rear
Scratched
25 to 100mm Thru Paint



No Image

15: Bumper Rear
Scratched
Over 25mm Not Thru Paint




16: Roof
Dented
Between 10mm + 30mm



17: Boot Lid
Chipped
1 To 5



18: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



20: Wheel osr
Scratched
Over 50mm




21: Door osr
Dented
Over 2 UpTo 10mm

No Image

22: Door osr
Scratched
Over 25mm Not Thru Paint



23: Door osf
Dented
Over 30mm



24: Wing osf
Chipped
1 To 5



25: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



26: Wheel osf
Scratched
Over 50mm



27: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK