

VEHICLE INSPECTION REPORT

LX11RFE

Volkswagen Golf 1.4 TSI Match 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	15/04/2011
Year	2011
Mileage	109,597 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	WVWZZZ1KZBW252152

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	11
Last service date	05/07/2024

Last service miles	101,054
MOT Due	17/07/2026
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE. Last service 05/07/2024 at 101054 miles (11 services (4 main dealer). Bulb light on dash

Bonnet heat shield damaged

Tyres

NSF	FIRESTONE	4.0mm
NSR	BUDGET	4.0mm
OSF	FIRESTONE	4.0mm
OSR	YOKOHAMA	3.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Dented
Between 10mm + 30mm

No Image


3: Boot Lid
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel osr
Dented
With Paint Damage



5: Wheel osr
Scratched
Over 50mm



6: Door osr
Dented
Over 30mm



7: Door osf
Poor Previous Repair
Poor Paint



8: Wing osf
Chipped
1 To 5



9: Screen Front
Chipped
UpTo 10mm



10: Bonnet
Chipped
Multiple Chips



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Bumper Front Moulding
Broken
Replace



13: Wing nsf
Chipped
1 To 5

No Image


14: Wing nsf
Scratched
Over 25mm Not Thru Paint



15: Wheel nsf
Scratched
Over 50mm




16: Door nsf
Poor Previous Repair
Poor Paint



17: Door nsr
Dented
2 Or Less UpTo 10mm

No Image

18: Door nsr
Scratched
Over 25mm Not Thru Paint



19: Qtr Panel nsr
Dented
With Paint Damage



20: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK