

## VEHICLE INSPECTION REPORT

DY16HVC

### Vauxhall Astra 1.4T 16V 150 Elite 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

#### Details

Reg. date	25/05/2016
Year	2016
Mileage	53,341 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	W0LBE6EC9G8060904

Body Style	Hatchback
Keys	1
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	01/02/2024

Last service miles	44,425
MOT Due	24/04/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE. Last service 01/02/2024 at 44425 miles (3 services). Low clutch  
Sticking clutch pedal  
Service due message displayed

#### Tyres


NSF	LAUFENN	5.0mm
NSR	AVON	5.0mm
OSF	LAUFENN	5.0mm
OSR	AVON	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Side airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- ESP
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Chipped  
1 To 5



5: Door nsr  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint




10: Tailgate  
Scratched  
UpTo 25mm Thru Paint



11: Wheel osr  
Scratched  
Up To 50mm




12: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



13: Door osr  
Dented  
Between 10mm + 30mm



14: Door osr  
Scratched  
Over 25mm Thru Paint



15: Door osf  
Scratched  
Over 25mm Thru Paint



16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Scratched  
UpTo 25mm Thru Paint

## Interior

Carpet Condition  
Seat Condition

Average  
Average

Upholstery Condition  
Odour

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK