

VEHICLE INSPECTION REPORT

DW18SGY

Vauxhall Mokka X 1.4T ecoTEC Elite Nav 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	31/07/2018
Year	2018
Mileage	84,543 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	W0VJD7E89JB708890

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	1
Last service date	07/11/2022

Last service miles	46,499
MOT Due	19/11/2026
Gearbox	MANUAL
Gears	6
Doors	5

Last service 07/11/2022 at 46,499 miles- 1 service. Print Wipers faulty

Tyres

NSF	WESTLAKE	5.0mm
NSR	TIGAR	5.0mm
OSF	WESTLAKE	5.0mm
OSR	WESTLAKE	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Poor Previous Repair
Poor Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Scratched
UpTo 25mm Thru Paint

No Image

12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Dented
Between 10mm + 30mm




15: Door osf
Dented
Over 30mm




16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Up To 50mm



18: Screen Front
Chipped
Over 10mm



19: Roof
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK