

VEHICLE INSPECTION REPORT

LC60FOK

Honda Jazz 1.4 i-VTEC EX 5dr i-SHIFT Auto

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	29/11/2010
Year	2010
Mileage	32,163 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	SHHGG6880BU010522

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	12
Last service date	29/11/2025

Last service miles	31,812
MOT Due	21/07/2026
Gearbox	SEMI AUTO
Gears	6
Doors	5

last service 29/11/25 @ 31,812 miles (12 services 8 main dealer) book


Tyres



NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


• Cruise control	• PAS	• Rear wiper	• Steering wheel mounted controls
• Audio remote control	• Radio/CD	• Body coloured bumpers	• Electric door mirrors
• Air conditioning	• Climate control	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear electric windows	• Metallic Paint	• ABS
• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag	• Central locking
• Remote central locking	• Cloth seat trim	• Alloy wheels	

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wing nsf
Dented
Over 2 UpTo 10mm



5: Wheel nsf
Scratched
Over 50mm

6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Door nsf
Scratched
UpTo 25mm Not Thru Paint

8: Door nsr
Dented
Over 30mm



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Chipped
Multiple Chips

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Poor Previous Repair
Poor Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Poor Previous Repair
Poor Paint



17: Door osf
Dented
Over 2 UpTo 10mm

No Image

18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK