

VEHICLE INSPECTION REPORT

GV16KZK

Toyota Avensis 1.8 Business Edition Plus 4dr

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	29/07/2016	Body Style	Saloon	Last service miles	130,085
Year	2016	Keys	2	MOT Due	21/07/2026
Mileage	170,452 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BRONZE	Number of stamps	13	Doors	4
VIN	SB1BG76L60E128281	Last service date	30/05/2023		

£65 ADDITIONAL FEE

Last service 30/05/2023 at 130,085 miles, was recorded as 209,352km- 13 main dealer services. Book MOTs recorded in Km since 2023 Heath shield rattle

Tyres




NSF	BRIDGESTONE	5.0mm
NSR	BUDGET	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Partial leather seat trim
- Navigation system
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Park assist camera
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Dented
Over 30mm



6: Qtr Panel nsr
Dented
Over 30mm



7: Wheel nsr
Scratched
Up To 50mm



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Fog Lamp osr
Broken
Replace



10: Wheel osr
Corroded
Light



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Dented
Over 30mm



13: Wheel osr
Scratched
Over 50mm



14: Wing osr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK