

VEHICLE INSPECTION REPORT

GU23JFK

Toyota C-Hr 1.8 Hybrid GR Sport 5dr CVT

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE
2

Details

Reg. date	01/03/2023
Year	2023
Mileage	18,046 Miles Warranted
Fuel Type	Hybrid Electric
Colour	GREY/BLACK
VIN	NMTK33BX10R249270

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	2
Last service date	06/03/2025

Last service miles	13,629
Gearbox	CVT
Gears	1
Doors	5

£65 ADDITIONAL FEE

Last service 06/03/2025 at 13,629 miles- 2 main dealer services. Book

Tyres

NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	3.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Cruise control
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos




1: Bumper Rear
Chipped
Multiple Chips

No Image

2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Dented
Over 2 UpTo 10mm



4: Qtr Panel osr
Chipped
1 To 5



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Door osr
Dented
Over 2 UpTo 10mm




8: Door osr
Scratched
Over 25mm Not Thru Paint



9: Door osf
Chipped
1 To 5



10: Wing osf
Chipped
1 To 5



11: Wheel osf
Scratched
Up To 50mm



12: Bonnet
Chipped
1 To 5



13: Bumper Front
Chipped
Multiple Chips

No Image

14: Bumper Front
Scratched
Over 25mm Not Thru Paint



15: Wing nsf
Chipped
1 To 5



16: Wheel nsf
Scratched
Up To 50mm



17: Door nsf
Dented
2 Or Less UpTo 10mm



18: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK