

VEHICLE INSPECTION REPORT

GV17VBM

Ford Fiesta 1.1 Zetec 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 5

Details

Reg. date	22/07/2017
Year	2017
Mileage	70,852 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	WF0JXXGAHJHR52202

Body Style	Hatchback
Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	6
Last service date	25/07/2025

Last service miles	68,185
MOT Due	26/07/2026
Gearbox	MANUAL
Gears	5
Doors	5

£65 ADDITIONAL FEE

Last Service - 25.07.2025 at 68185 miles (6 services)

Tyres



NSF	SUNNY	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Fog Lamp Surround os
Missing
Replace



4: Wing nsf
Chipped
1 To 5



No Image

5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Chipped
1 To 5



No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Dented
With Paint Damage




10: Qtr Panel nsr
Dented
With Paint Damage




11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint




14: Qtr Panel osr
Poor Previous Repair
Paint Flake



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
With Paint Damage



17: Door osf
Dented
Over 30mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK