

VEHICLE INSPECTION REPORT

GL67VHN

Volkswagen Polo 1.2 TSI Match Edition 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	16/12/2017
Year	2017
Mileage	80,702 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	WVWZZZ6RZHU094438

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	25/11/2025

Last service miles	79,489
MOT Due	15/12/2026
Gearbox	MANUAL
Gears	5
Doors	5

£65 ADDITIONAL FEE. Last service 25/11/2025 at 79489 miles (8 services (1 main dealer)).

Tyres




NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	3.0mm
OSF	CONTINENTAL	2.0mm
OSR	HANKOOK	2.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• PAS
• Rear parking sensor	• Rear wiper	• Steering wheel mounted controls	• Digital radio
• Body coloured bumpers	• Electric door mirrors	• Front fog lights	• Air conditioning
• Folding rear seats	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear electric windows	• Rear headrests	• Steering wheel rake adjustment	• Steering wheel reach adjustment
• Metallic Paint	• 3x3 point rear seat belts	• ABS	• Drivers airbag
• Isofix child seat anchor points	• Passenger airbag	• Side airbags	• Central locking
• Remote central locking	• Cloth seat trim	• Alloy wheels	

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Dented
With Paint Damage



3: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

No Image

4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Wheel osr
Scratched
Over 50mm



6: Door osr
Scratched
Over 25mm Thru Paint



7: Door osf
Chipped
Multiple Chips




8: Wing osf
Chipped
1 To 5

No Image

9: Wing osf
Scratched
Over 25mm Not Thru Paint



10: Wheel osf
Scratched
Over 50mm



11: Bonnet
Chipped
Multiple Chips



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Wing nsf
Dented
With Paint Damage




14: Wheel nsf
Scratched
Over 50mm



15: Door nsf
Chipped
Multiple Chips



16: Door nsr
Chipped
1 To 5



17: Door nsr
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel nsr
Chipped
1 To 5



19: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



20: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK