

VEHICLE INSPECTION REPORT

KF21WZW

Ford Focus 1.5 EcoBlue 120 ST-Line 5dr Auto

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 2

Details

Reg. date	11/08/2021
Year	2021
Mileage	18,804 Miles Warranted
Fuel Type	Diesel
Colour	BLACK
VIN	WF0NXXGCHNMR52625

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	1
Last service date	21/08/2025

Last service miles	17,464
MOT Due	27/08/2026
Gearbox	AUTOMATIC
Gears	8
Doors	5

£65 ADDITIONAL FEE

last service 21/8/25 @ 17,464 miles (1 service) print

Tyres



NSF	DAVANTI	3.0mm
NSR	BUDGET	3.0mm
OSF	DAVANTI	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Navigation system
• PAS	• Rear parking sensor	• Rear wiper	• Steering wheel mounted controls
• Audio remote control	• Digital radio	• Body coloured bumpers	• Electric door mirrors
• Air conditioning	• Climate control	• Front armrest	• Front electric windows
• Front head restraints	• Height adjustable drivers seat	• Rear electric windows	• Rear headrests
• Metallic Paint	• 3x3 point rear seat belts	• ABS	• Drivers airbag
• Isofix child seat anchor points	• Passenger airbag	• Side airbags	• Traction control
• Central locking	• Remote central locking	• Cloth seat trim	• Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm




11: Bumper Rear
Chipped
Multiple Chips

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint




13: Boot Lid
Dented
Over 2 UpTo 10mm




14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Chipped
1 To 5



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Chipped
1 To 5



19: Wing osf
Dented
Over 2 UpTo 10mm



20: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK