

VEHICLE INSPECTION REPORT

KM65JXF

Mini Clubman 1.5 Cooper 6dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	27/10/2015
Year	2015
Mileage	105,370 Miles Warranted
Fuel Type	Petrol
Colour	BLUE
VIN	WMWLN320102B98847

Body Style	Estate
Keys	1
Service history	Yes
Service documents	Electronic & Paper
Number of stamps	3
Last service date	21/10/2025

Last service miles	104,479
MOT Due	18/11/2026
Gearbox	MANUAL
Gears	6

£65 ADDITIONAL FEE

Last service 21/10/2025 at 104,479 miles- 3 services. Print and recorded on on- board system

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	POWERTRAC	5.0mm
OSF	BUDGET	5.0mm
OSR	AVON	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



3: Bumper Front
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
1 To 5



8: Door nsr
Poor Previous Repair
Rippled UpTo 30%



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Dented
With Paint Damage



12: Tailgate
Dented
Over 30mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osr
Dented
Between 10mm + 30mm



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK