

# VEHICLE INSPECTION REPORT

LL16YYM

## Seat Ibiza 1.4 EcoTSI 150 FR 3dr

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

### Details

Reg. date	30/06/2016
Year	2016
Mileage	119,480 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	VSSZZ6JZGR075123

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	9
Last service date	24/06/2025

Last service miles	114,601
MOT Due	30/06/2026
Gearbox	MANUAL
Gears	6
Doors	3

Last Service - 24.06.2025 at 114601 miles (9 main dealer services)


### Tyres

NSF	GT RADIAL	3.0mm
NSR	DUNLOP	3.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


<ul style="list-style-type: none"> <li>Bluetooth connection</li> <li>Audio remote control</li> <li>Climate control</li> <li>Rear headrests</li> <li>Drivers airbag</li> <li>Remote central locking</li> </ul>	<ul style="list-style-type: none"> <li>PAS</li> <li>Body coloured bumpers</li> <li>Front electric windows</li> <li>Solid Paint</li> <li>Isofix child seat anchor points</li> <li>Cloth seat trim</li> </ul>	<ul style="list-style-type: none"> <li>Rear wiper</li> <li>Electric door mirrors</li> <li>Front head restraints</li> <li>3x3 point rear seat belts</li> <li>Passenger airbag</li> <li>Alloy wheels</li> </ul>	<ul style="list-style-type: none"> <li>Steering wheel mounted controls</li> <li>Air conditioning</li> <li>Height adjustable drivers seat</li> <li>ABS</li> <li>Central locking</li> </ul>
---	---	---	---

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wing nsf  
Chipped  
1 To 5



4: Wheel nsf  
Scratched  
Up To 50mm



5: Door nsf  
Poor Previous Repair  
Poor Paint



6: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



7: Wheel nsr  
Scratched  
Up To 50mm




8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

# No Image

9: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



10: Boot Lid  
Dented  
2 Or Less UpTo 10mm




11: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm

# No Image

12: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



13: Wheel osr  
Scratched  
Up To 50mm



14: Door osf  
Dented  
Over 2 UpTo 10mm



15: Wing osf  
Scratched  
UpTo 25mm Thru Paint

No Image

16: Wing osf  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osf  
Scratched  
Up To 50mm



18: Screen Front  
Chipped  
UpTo 10mm



19: Carpets Front  
Torn  
Over 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK