

VEHICLE INSPECTION REPORT

GX15UZW

Ford Fiesta 1.0 EcoBoost 140 Zetec S Red 3dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	15/06/2015
Year	2015
Mileage	110,417 Miles Warranted
Fuel Type	Petrol

Colour	RED
VIN	WF0CXXGAKCFE27044
Body Style	Hatchback
Keys	1

MOT Due	21/03/2026
Gearbox	MANUAL
Gears	5
Doors	3

£65 ADDITIONAL FEE


Tyres


NSF	ROADSTONE	5.0mm
NSR	WESTLAKE	5.0mm
OSF	RAPID	5.0mm
OSR	WESTLAKE	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Full size spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Fog Lamp Surround ns
Broken
Replace




3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Bumper Rear
Chipped
1 To 5



10: Other
N/A
N/A




11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm




13: Sill Panel Trim os
Scratched (Painted)
Over 25mm Thru Paint




14: Door osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Chipped
Multiple Chips



17: Screen Front
Chipped
Over 10mm



18: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK