

VEHICLE INSPECTION REPORT

WR19LKF

Mitsubishi Eclipse Cross 1.5 4 5dr CVT 4WD

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	25/03/2019
Year	2019
Mileage	40,389 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	JMAXTGK1WJZ004516

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	6
Last service date	21/03/2025

Last service miles	38,483
MOT Due	10/06/2026
Gearbox	CVT
Gears	1
Doors	5

£100 ADDITIONAL FEE.

Last service 21/03/2025 at 38,483 miles- 6 services (3 main dealer) Book

Tyres


NSF	SAILUN	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Dented
Between 10mm + 30mm



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



9: Door nsf
Dented
With Paint Damage



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osr
Scratched
UpTo 25mm Thru Paint



16: Door osf
Dented
Between 10mm + 30mm



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK