

## VEHICLE INSPECTION REPORT

**GX71WRA**

### Volkswagen Polo 1.0 EVO 80 Match 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

#### Details

Reg. date	24/09/2021
Year	2021
Mileage	56,758 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	WVWZZZAWZMU100532

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	4
Last service date	24/05/2024

Last service miles	35,181
MOT Due	02/10/2026
Gearbox	MANUAL
Gears	5
Doors	5

#### £65 ADDITIONAL FEE.

Last service 24/05/2024 at 35,181 miles- 4 main dealer services. Print Eml on - vehicle plugged in and reads (vag engine oil temperature sensor circuit high input)

Oil sensor light on dash

Service due

#### Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	KUMHO	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips

# No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wing nsf  
Chipped  
1 To 5



5: Wheel nsf  
Scratched  
Up To 50mm



6: Door nsf  
Dented  
With Paint Damage



7: Sill ns  
Dented  
With Paint Damage



8: Door nsr  
Scratched  
UpTo 25mm Thru Paint

# No Image



9: Door nsr  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsr  
Scratched  
Up To 50mm



11: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm


# No Image

12: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



13: Bumper Rear  
Scratched  
Over 100mm Thru Paint

14: Boot Lid  
Chipped  
1 To 5



15: Qtr Panel osr  
Chipped  
1 To 5

No Image

16: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osr  
Scratched  
Up To 50mm



18: Door osr  
Chipped  
1 To 5



19: Door osr  
Dented  
Over 2 UpTo 10mm



20: Door osf  
Chipped  
1 To 5



21: Wing osf  
Chipped  
1 To 5



22: Roof  
Dented  
Hail - Moderate



23: Wheel osf  
Scratched  
Up To 50mm



24: Screen Front  
Chipped  
UpTo 10mm

## Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK