

VEHICLE INSPECTION REPORT

GX16EOJ

Volkswagen Touran 1.6 TDI SE Family 5dr DSG

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	01/03/2016
Year	2016
Mileage	129,658 Miles Warranted
Fuel Type	Diesel
Colour	SILVER
VIN	WVGZZZ1TZGW555479

Body Style	MPV
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	25/11/2025

Last service miles	78,550
MOT Due	28/02/2026
Gearbox	SEMI AUTO
Gears	6

£65 ADDITIONAL FEE.

Last service 25/11/2025 at 78,550 miles- 8 services (6 main dealer) Book and print
Cambelt replaced 28/02/2022 at 41,23 miles Mirror adjuster broken

Tyres


NSF	RAPID	3.0mm
NSR	HANKOOK	3.0mm
OSF	RAPID	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- PAS
- Audio remote control
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Dented
Over 2 UpTo 10mm



7: Door nsf
Poor Previous Repair
Poor Paint



4: Bumper Front Moulding
Broken
Replace



6: Wheel nsf
Scratched
Over 50mm



8: Door nsf
Poor Previous Repair
Poor Paint



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint




10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Poor Previous Repair
Poor Paint



12: Boot Lid
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Poor Previous Repair
Poor Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		