

## VEHICLE INSPECTION REPORT

DV63PZK

### Seat Leon 1.4 TSI FR 5dr [Technology Pack]

Inspection	Vehicle		nama GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

#### Details

Reg. date	05/11/2013	Body Style	Hatchback	Last service miles	20,171
Year	2013	Keys	2	MOT Due	24/03/2026
Mileage	123,647 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	3	Doors	5
VIN	VSSZZZ5FZER043502	Last service date	27/10/2016		

£65 ADDITIONAL FEE.

Last service 27/10/2016 at 20,171 miles- 3 main dealer services. Print

#### Tyres


NSF	BUDGET	2.0mm
NSR	RAPID	4.0mm
OSF	SUNNY	3.0mm
OSR	PIRELLI	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Audio remote control
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
Over 100mm Thru Paint




2: Qtr Panel osr  
Poor Previous Repair  
Poor Paint




3: Door osr  
Poor Previous Repair  
Poor Paint



4: Wheel osr  
Scratched  
Over 50mm




5: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



6: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



7: Roof  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Chipped  
1 To 5

# No Image




10: Wheel nsr  
Scratched  
Over 50mm

9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



11: Door nsf  
Scratched  
Over 25mm Not Thru Paint

# No Image



12: Door nsf  
Scratched  
Over 25mm Not Thru Paint

13: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

14: Door osf  
Scratched  
UpTo 25mm Thru Paint

# No Image

15: Door osf  
Scratched  
Over 25mm Not Thru Paint




16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Chipped  
1 To 5

# No Image

18: Wing osf  
Scratched  
Over 25mm Not Thru Paint



19: Bonnet  
Chipped  
Multiple Chips



20: Bumper Front  
Scratched  
Over 100mm Thru Paint



21: Wheel nsf  
Scratched  
Over 50mm

No Image

22: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		