

VEHICLE INSPECTION REPORT

GL22KFV

Kia E-Niro 150kW 2 Long Range 64kWh 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/06/2022	Body Style	Estate	Last service miles	21,389
Year	2022	Keys	1	MOT Due	29/06/2026
Mileage	38,534 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Printout	Gears	1
Colour	GREY	Number of stamps	2		
VIN	KNACB81GUN5155369	Last service date	30/11/2023		

Last service 30/11/2023 at 21,389 miles- 2 services. Print Both types of charging cables in boot



Tyres

NSF	GOODYEAR	4.0mm
NSR	MICHELIN	4.0mm
OSF	GOODYEAR	4.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm



5: Wing nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsr
Chipped
1 To 5

No Image


8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Bumper Rear
Chipped
Multiple Chips



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osr
Dented
2 Or Less UpTo 10mm



14: Door osf
Dented
2 Or Less UpTo 10mm

No Image

15: Door osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK