

VEHICLE INSPECTION REPORT

TGZ9462

Toyota Yaris 1.5 Hybrid Excel 5dr CVT

| Inspection | Vehicle | nama GRADE 2 |
|-----------------|---------|--------------------|
| Serious Damage? | VAT | VAT Qualifying |
| No | V5 | Present |

Details

| | | | | | |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 08/09/2021 | Body Style | Hatchback | Last service miles | 12,958 |
| Year | 2021 | Keys | 2 | MOT Due | 07/09/2026 |
| Mileage | 71,937 Miles Warranted | Service history | Yes | Gearbox | CVT |
| Fuel Type | Hybrid Electric | Service documents | Service Book | Gears | 1 |
| Colour | SILVER | Number of stamps | 2 | Doors | 5 |
| VIN | VNKKBAC320A188309 | Last service date | 23/12/2022 | | |

Last service 23/12/2022 at 12958 miles (2 main dealer services).

Tyres



| | | |
|-------|-------|-------|
| NSF | NEXEN | 5.0mm |
| NSR | AVON | 5.0mm |
| OSF | NEXEN | 5.0mm |
| OSR | NEXEN | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- PAS
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Partial leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
Between 10mm + 30mm



6: Wheel nsr
Scratched
Over 50mm



7: Tailgate
Dented
Between 10mm + 30mm



8: Qtr Panel osr
Dented
Between 10mm + 30mm



9: Wheel osf
Scratched
Up To 50mm



10: Door osf
Chipped
Edge Chip



11: Screen Front
Chipped
UpTo 10mm



12: Wheel osf
Scratched
Over 50mm

Interior

| | |
|------------------|---------|
| Carpet Condition | Average |
| Seat Condition | Average |

| | |
|----------------------|---------|
| Upholstery Condition | Average |
| Odour | No |

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|----------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| No Excessive Smoking | | | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |