



VEHICLE INSPECTION REPORT

GP18NNM

Volkswagen Tiguan 2.0 TSi 180 4Motion SEL 5dr DSG

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	05/03/2018	Body Style	Estate	Last service miles	81,755
Year	2018	Keys	2	MOT Due	04/03/2026
Mileage	86,573 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	9		
VIN	WVGZZZ5NZJW908410	Last service date	16/09/2025		

£65 ADDITIONAL FEE.

Last service 16/09/2025 at 81,755 miles- 9 main dealer services. Print

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Curtain airbags
- Side airbags
- Cloth seat trim
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm



5: Wing nsf
Chipped
1 To 5

No Image

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Dented
Over 2 Up To 10mm



8: Door nsr
Dented
2 Or Less Up To 10mm

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Up To 50mm

No Image



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image




13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

14: Bumper Rear Moulding
Broken
Replace



15: Boot Lid
Dented
2 Or Less Up To 10mm



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Scratched
Up To 50mm



18: Door osr
Chipped
1 To 5




19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Dented
Between 10mm + 30mm

No Image



21: Wing osf
Scratched
Over 25mm Not Thru Paint

22: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		