

VEHICLE INSPECTION REPORT

GN63YDZ

Vauxhall Astra Gtc 1.4T 16V SRi 3dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	TBC

nama
GRADE 5

Details

Reg. date	24/09/2013
Year	2013
Mileage	105,611 Miles Warranted
Fuel Type	Petrol

Colour	RED
VIN	W0LPF2EUXEG002100
Body Style	Hatchback
Keys	1

MOT Due	12/06/2026
Gearbox	MANUAL
Gears	6
Doors	3

£65 ADDITIONAL FEE. Coolant level low and oil service due message displayed

Tyres


NSF	AVON	4.0mm
NSR	AVON	5.0mm
OSF	AVON	4.0mm
OSR	AVON	5.0mm
Spare		

Features


- Cruise control
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Solid Paint
- ESP
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Dented
With Paint Damage




4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint




8: Tailgate
Dented
With Paint Damage



9: Roof
Dented
Between 10mm + 30mm

No Image


10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Wing osf
Scratched
Over 25mm Thru Paint



14: Wheel osf
Scratched
Up To 50mm



15: Screen Front
Chipped
UpTo 10mm



16: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK