

## VEHICLE INSPECTION REPORT

RV15WBF

### Mercedes-Benz A Class A200 AMG Sport 5dr Auto

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
	V5	Present

#### Details

Reg. date	26/03/2015	Body Style	Hatchback	Last service miles	60,623
Year	2015	Keys	2	MOT Due	06/07/2026
Mileage	60,726 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	RED	Number of stamps	11	Doors	5
VIN	WDD1760432V065735	Last service date	09/01/2026		

last service 9/1/26 @ 60,623 miles (11 services 2 main dealer) book and print

#### Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Partial leather seat trim
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Poor Previous Repair  
Poor Paint




2: Boot Lid  
Dented  
With Paint Damage



3: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm

No Image

4: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



5: Door osr  
Poor Previous Repair  
Poor Paint



6: C Post os  
Poor Previous Repair  
Poor Paint



7: Door osf  
Poor Previous Repair  
Poor Paint



8: Wing osf  
Poor Previous Repair  
Poor Paint



9: Bonnet  
Chipped  
1 To 5



10: Bumper Front  
Poor Previous Repair  
Poor Paint



11: Wing nsf  
Chipped  
1 To 5



12: Wheel nsf  
Scratched  
Over 50mm



13: Wheel osf  
Scratched  
Over 50mm



14: Wheel osr  
Scratched  
Over 50mm



15: Door nsf  
Chipped  
1 To 5

No Image



17: Door nsr  
Chipped  
1 To 5

16: Door nsf  
Scratched  
Over 25mm Not Thru Paint

No Image



19: Wheel nsr  
Scratched  
Up To 50mm

18: Door nsr  
Scratched  
Over 25mm Not Thru Paint



20: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK