

VEHICLE INSPECTION REPORT

LY08WUV

Volkswagen Polo 1.4 Match 80 5dr Auto

Inspection	Vehicle		GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	31/07/2008	Body Style	Hatchback	Last service miles	44,852
Year	2008	Keys	1	MOT Due	13/08/2026
Mileage	47,539 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	13	Doors	5
VIN	WVWZZZ9NZ9Y036136	Last service date	02/08/2023		

Last service 02/08/2023 at 44852 miles (13 services (3 main dealer). Book & print. EML light on car has been plugged in and detects

Knock sensor 1 circuit high input bank 1 or single sensor

Tapping engine when revved

Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Rear headrests
- Central locking
- Radio/CD
- Climate control
- Metallic Paint
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front Moulding
Broken
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsf
Scratched
UpTo 25mm Not Thru Paint



8: Door nsr
Dented
2 Or Less UpTo 10mm

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Poor Previous Repair
Poor Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Dented
Over 2 UpTo 10mm




14: Qtr Panel osr
Rusted
UpTo 5mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Over 2 UpTo 10mm



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Poor Previous Repair
Poor Paint



19: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm



22: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK