

VEHICLE INSPECTION REPORT

GJ68HSK

Volkswagen Transporter 2.0 TDI BMT 102 Trendline Van Euro 6

Inspection	Vehicle	nama GRADE 4
Serious Damage? No	VAT Plus VAT	
	V5 Present	

Details

Reg. date	27/09/2018	Body Style	Van With Side Windows	Last service miles	69,867
Year	2018	Keys	2	MOT Due	26/09/2026
Mileage	81,041 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	5
Colour	SILVER	Number of stamps	3		
VIN	WV1ZZZ7HZJH203995	Last service date	11/09/2024		

£100 ADDITIONAL FEE

Last service 11/09/2024 at 69,867 miles- 3 services. Print Radio comes up with Skoda while starting

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	Damaged
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Front electric windows
- Central locking
- Navigation system
- Metallic Paint
- Cloth seat trim
- Radio/CD
- Drivers airbag
- Air conditioning
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
With Paint Damage



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%




11: Boot Lid
Dented
With Paint Damage



12: Qtr Panel osr
Dented
Over 30mm



13: Wheel osr
Scratched
Over 50mm



14: Roof
Dented
Between 10mm + 30mm



15: Door osf
Dented
Over 2 UpTo 10mm

No Image

16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Tyre osf
Damaged
Replace



18: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK