

# VEHICLE INSPECTION REPORT

FY08UZE

## BMW 1 Series 116i M Sport 3dr [122]

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

### Details

Reg. date	21/03/2008	Body Style	Hatchback	Last service miles	105,900
Year	2008	Keys	1	MOT Due	10/07/2026
Mileage	121,246 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	8	Doors	3
VIN	WBAUB72020VF96782	Last service date	17/05/2024		

Last service 17/05/2024 at 105,900 miles- 8 services. Book Aftermarket radio fitted  
Engine tapping

### Tyres


NSF	BRIDGESTONE	5.0mm
NSR	BUDGET	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Partial leather seat trim
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover off  
Torn  
Over 3mm



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Poor Previous Repair  
Poor Paint



4: Bumper Front  
Insecure  
Action Required



5: Wing nsf  
Poor Previous Repair  
Rippled UpTo 30%



6: Wheel nsf  
Scratched  
Over 50mm



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsf  
Dented  
With Paint Damage



9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Dented  
With Paint Damage



11: Qtr Panel osr  
Chipped  
Over 5mm



12: Wheel osr  
Scratched  
Over 50mm




13: Door osf  
Poor Previous Repair  
Rippled UpTo 30%



14: Wing osf  
Poor Previous Repair  
Rippled UpTo 30%



15: Wheel osf  
Scratched  
Over 50mm



16: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Poor

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK