

## VEHICLE INSPECTION REPORT

GU69WUK

### Citroen Grand C4 Spacetourer 1.2 PureTech 130 Feel Plus 5dr

Inspection	Vehicle	nama
Serious Damage?	VAT	Margin
No	V5	Present

#### Details

Reg. date	14/01/2020	Body Style	MPV	Last service miles	46,960
Year	2020	Keys	2	MOT Due	21/01/2027
Mileage	52,474 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	3		
VIN	VF73AHNS2KJ894661	Last service date	02/01/2025		

Last Service - 02.01.2025 at 46960 miles (3 main dealer services)

#### Tyres

NSF	TRIANGLE	3.0mm
NSR	MICHELIN	2.0mm
OSF	BUDGET	2.0mm
OSR	MICHELIN	2.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front  
Scratched  
UpTo 25mm Thru Paint

No Image

4: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Chipped  
1 To 5



7: Door nsf  
Chipped  
1 To 5



8: Door nsr  
Chipped  
1 To 5



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Chipped  
Multiple Chips



13: Boot Lid  
Dented  
2 Or Less UpTo 10mm



14: Qtr Panel osr  
Dented  
Over 30mm



15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Poor Previous Repair  
Poor Paint



17: Door osf  
Dented  
Over 2 UpTo 10mm

No Image


18: Door osf  
Scratched  
Over 25mm Not Thru Paint



19: Wing osf  
Dented  
Between 10mm + 30mm



20: Wheel osf  
Scratched  
Over 50mm



21: Screen Front  
Chipped  
UpTo 10mm

No Image

22: Door osr  
Dented  
Over 2 UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK