

## VEHICLE INSPECTION REPORT

EN19NAE

### VAUXHALL INSIGNIA 1.5T Tech Line Nav 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	VAT Qualifying
V5	Photocopy

nama  
GRADE 4

#### Details

Reg. date	16/05/2019
Year	2019
Mileage	73,440 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	W0VZT6EB8K1062812

Body Style	Hatchback
Keys	1
Service history	Yes
Service documents	Printout
Number of stamps	5
Last service date	25/11/2024

Last service miles	55,221
MOT Due	26/01/2027
Gearbox	MANUAL
Gears	6
Doors	5

Last Service - 25.11.2024 at 55221 miles (5 services)

Copy V5 only

#### Tyres



NSF	AVON	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image

2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

# No Image

3: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




4: Qtr Panel osr  
Dented  
Over 30mm



5: Wheel osr  
Scratched  
Over 50mm




6: Door osr  
Chipped  
1 To 5



7: Door osr  
Scratched  
Over 25mm Not Thru Paint



8: Door osf  
Chipped  
Multiple Chips



9: Wing osf  
Chipped  
1 To 5

No Image


10: Wing osf  
Scratched  
Over 25mm Not Thru Paint



11: Wheel osf  
Scratched  
Over 50mm



12: Bumper Front  
Chipped  
Multiple Chips



13: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



14: Bonnet  
Chipped  
1 To 5



15: Bumper Front  
Hole  
UpTo 25mm



16: Wing nsf  
Poor Previous Repair  
Poor Paint



17: Wheel nsf  
Scratched  
Over 50mm



18: Door nsr  
Scratched  
UpTo 25mm Thru Paint



19: Door nsf  
Dented  
Over 2 UpTo 10mm



20: Door nsr  
Dented  
2 Or Less UpTo 10mm

# No Image

21: Door nsr  
Scratched  
Over 25mm Not Thru Paint



22: Qtr Panel nsr  
Dented  
Over 30mm



23: Wheel nsr  
Scratched  
Over 50mm

# No Image

24: Roof  
Scratched  
Over 25mm Not Thru Paint

## Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK