

# VEHICLE INSPECTION REPORT

LX06VEA

## Peugeot 1007 1.6 Sport 3dr 2-Tronic

Inspection	Vehicle		GRADE 3
Serious Damage?	VAT	Margin	
No	V5	Present	

### Details

Reg. date	08/03/2006	Body Style	Hatchback	Last service miles	32,304
Year	2006	Keys	3	MOT Due	05/03/2026
Mileage	33,483 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	5	Doors	3
VIN	VF3KMNFC20047961	Last service date	15/10/2025		

### HAND CONTROLS FITTED.

Alternator replaced 07/01/2025 at 29375 miles.

Last service 15/10/2025 at 32304 miles (5 services) Book & print. Hand control for throttle and brake  
Only two keys work

### Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Front head restraints
- ABS
- Central locking
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Front armrest
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips

# No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Up To 50mm



5: Wing nsf  
Scratched  
UpTo 25mm Thru Paint

# No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Poor Previous Repair  
Poor Paint




8: Qtr Panel nsf  
Poor Previous Repair  
Poor Paint



9: Wheel nsr  
Scratched  
Up To 50mm



10: Bumper Rear  
Chipped  
Multiple Chips



11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



12: Boot Lid  
Chipped  
1 To 5



13: Qtr Panel osr  
Dented  
Over 30mm



14: Wheel osr  
Scratched  
Up To 50mm



15: Door osf  
Poor Previous Repair  
Poor Paint



16: Wing osf  
Chipped  
1 To 5



17: Wing osf  
Scratched  
Over 25mm Not Thru Paint



18: Wheel osf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK