

VEHICLE INSPECTION REPORT

VO18MHZ

Volkswagen Golf 1.6 TDI GT 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	16/03/2018
Year	2018
Mileage	98,466 Miles Warranted
Fuel Type	Diesel
Colour	BLUE
VIN	WVWZZAUZJW152877

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	1
Last service date	04/06/2025

Last service miles	89,383
MOT Due	31/03/2026
Gearbox	MANUAL
Gears	5
Doors	5

£65 ADDITIONAL FEE

Last service 04/06/2025 at 89,383 miles- 1 service. Print

Tyres



NSF	BUDGET	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	SUNNY	3.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Door nsr
Chipped
Multiple Chips



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Up To 50mm




11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Dented
Over 2 UpTo 10mm




14: Qtr Panel osr
Dented
Over 30mm




15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Scratched
UpTo 25mm Thru Paint



17: Door osr
Scratched
Over 25mm Not Thru Paint




18: Door osf
Poor Previous Repair
Poor Paint



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK