

## VEHICLE INSPECTION REPORT

OW17FTE

### Land Rover Discovery Sport 2.0 TD4 180 SE Tech 5dr Auto

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE  
3

#### Details

Reg. date	29/06/2017
Year	2017
Mileage	27,672 Miles Warranted
Fuel Type	Diesel
Colour	BLUE
VIN	SALCA2AN0HH713129

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	2
Last service date	10/09/2025

Last service miles	24,463
MOT Due	28/12/2026
Gearbox	AUTOMATIC
Gears	9

#### £65 ADDITIONAL FEE

Last service 10/09/2025 at 24,463 miles- 2 services. Print

#### Tyres

NSF	PIRELLI	Worn
NSR	PIRELLI	3.0mm
OSF	BUDGET	Worn
OSR	PIRELLI	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Audio remote control
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips

# No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



7: Door nsf  
Dented  
With Paint Damage



8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Wheel nsr  
Scratched  
Up To 50mm



10: Qtr Panel nsr  
Chipped  
1 To 5




11: Bumper Rear  
Chipped  
Multiple Chips

No Image

12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Boot Lid  
Dented  
Over 2 UpTo 10mm



14: Wheel osr  
Scratched  
Up To 50mm



15: Qtr Panel osr  
Chipped  
1 To 5



16: Door osr  
Dented  
Over 2 UpTo 10mm



17: Door osf  
Chipped  
1 To 5

No Image

18: Door osf  
Scratched  
Over 25mm Not Thru Paint



19: Wing osf  
Chipped  
1 To 5



20: Wheel osf  
Scratched  
Up To 50mm

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK