

# VEHICLE INSPECTION REPORT

GY15KPR

## Toyota Yaris 1.5 Hybrid Icon 5dr CVT

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

### Details

Reg. date	30/04/2015
Year	2015
Mileage	49,963 Miles Warranted
Fuel Type	Hybrid Electric

Colour	WHITE
VIN	VNKKD3D330A159003
Body Style	Hatchback
Keys	2

MOT Due	29/10/2026
Gearbox	CVT
Gears	1
Doors	5

Last Service - 24.06.2025 at 46857 miles (10 main dealer services)

### Tyres



NSF	GOODYEAR	4.0mm
NSR	BUDGET	3.0mm
OSF	GOODYEAR	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Central locking
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
Over 100mm Thru Paint



2: Bonnet  
Chipped  
1 To 5



3: Wing nsf  
Chipped  
1 To 5

No Image


4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Dented  
Over 2 UpTo 10mm



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Boot Lid  
Chipped  
1 To 5



13: Qtr Panel osr  
Dented  
With Paint Damage



14: Wheel osr  
Scratched  
Over 50mm



15: Door osr  
Dented  
With Paint Damage



16: Door osf  
Dented  
With Paint Damage



17: Wing osf  
Chipped  
1 To 5

No Image

18: Wing osf  
Scratched  
Over 25mm Not Thru Paint



19: Wheel osf  
Scratched  
Over 50mm



20: Roof  
Chipped  
Edge Chip

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK