

VEHICLE INSPECTION REPORT

GV12WOA

Seat Ibiza 1.2 TSI FR 5dr

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	31/07/2012	Body Style	Hatchback	Last service miles	102,417
Year	2012	Keys	2	MOT Due	14/09/2026
Mileage	105,072 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	13	Doors	5
VIN	VSSZZZ6JZDR064182	Last service date	02/09/2025		

£100 ADDITIONAL FEE

Last Service - 02.09.2025 at 102417 miles (13 services) Drivers interiors handle stiff to pull

Tyres




NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	FALKEN	3.0mm
OSR	FALKEN	3.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Dented
With Paint Damage



2: Bumper Front Moulding
Broken
Replace



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm




9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Boot Lid
Chipped
1 To 5



11: Qtr Panel osr
Dented
With Paint Damage



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Dented
With Paint Damage



14: Door osf
Dented
With Paint Damage



15: Roof
Dented
With Paint Damage



16: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Wing osf
Chipped
Multiple Chips



18: Wheel osf
Scratched
Over 50mm



19: Bonnet
Chipped
Multiple Chips



20: Screen Front
Chipped
UpTo 10mm



21: Door Pad nsf
Scuffed
Over 25mm



22: Door Pad osf
Scuffed
UpTo 25mm



23: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK