

VEHICLE INSPECTION REPORT

AF16UUL

Fiat 500 1.2 Pop 3dr

Cat: S

Inspection

Serious Damage? No

Vehicle

VAT Margin
V5

nama
GRADE 4

Details

| | | | | | |
|-----------|---------------------------|------------|-------------------|---------|------------|
| Reg. date | 16/03/2016 | Colour | WHITE | MOT Due | 29/06/2026 |
| Year | 2016 | VIN | ZFA3120000J546862 | Gearbox | MANUAL |
| Mileage | 53,233 Miles Warranted | Body Style | Hatchback | Gears | 5 |
| Fuel Type | Petrol | Keys | 1 | Doors | 3 |

£100 ADDITIONAL FEE.

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair

Tyres

| | | |
|-------|----------|-------|
| NSF | GOODRIDE | 5.0mm |
| NSR | MAZZINI | 5.0mm |
| OSF | GOODRIDE | 5.0mm |
| OSR | AUTOGRIp | 5.0mm |
| Spare | | |

Features


- PAS
- Media storage
- Front electric windows
- Metallic Paint
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front head restraints
- ABS
- Tyre pressure monitor
- Alloy wheels
- Service indicator
- Electric door mirrors
- Steering wheel rake adjustment
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Folding rear seats
- Steering wheel reach adjustment
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Roof
Dented
Over 30mm



11: Qtr Panel osr
Dented
Between 10mm + 30mm



12: Door osr
Dented
With Paint Damage



13: Wheel osr
Scratched
Over 50mm



14: Wing osr
Scratched
UpTo 25mm Thru Paint



15: Screen Front
Chipped
UpTo 10mm

Interior

| | | | |
|-------------------------|---------|-----------------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition | Average | Odour | No |

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |