



# VEHICLE INSPECTION REPORT

**GX65UNL**

## Toyota Auris 1.2T Icon 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/09/2015	Body Style	Hatchback	Last service miles	68,097
Year	2015	Keys	2	MOT Due	25/02/2026
Mileage	74,421 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	9	Doors	5
VIN	SB1MA3JE80E009496	Last service date	26/02/2025		

£100 ADDITIONAL FEE.

Last service 26/02/2025 at 68,097 miles- 9 services (5 main dealer) Book and print

### Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Chipped  
Edge Chip



6: Door nsr  
Scratched  
Up To 25mm Thru Paint



7: Wheel nsr  
Scratched  
Up To 50mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Wheel osr  
Scratched  
Over 50mm



10: Door osr  
Dented  
Between 10mm + 30mm



11: Door osf  
Dented  
Between 10mm + 30mm



12: Wheel osf  
Scratched  
Over 50mm



13: Wing osf  
Scratched  
UpTo 25mm Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK