



# VEHICLE INSPECTION REPORT

DG70EPF

## Audi A3 35 TFSI S Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/09/2020	Body Style	Hatchback	Last service miles	49,520
Year	2020	Keys	1	MOT Due	22/09/2026
Mileage	49,531 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	4	Doors	5
VIN	WAUZZZGY2MA019840	Last service date	28/11/2025		

£65 ADDITIONAL FEE.  
Last service 28/11/2025 at 49,520 miles- 4 main dealer services. Print


Tyres		
NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	4.0mm
OSF	NEXEN	2.0mm
OSR	GOODYEAR	3.0mm
Spare		

## Features


- Bluetooth connection
  - Rear wiper
  - Body coloured bumpers
  - Front armrest
  - Rear electric windows
  - ABS
  - Side airbags
  - Leather seat trim
- Cruise control
  - Steering wheel mounted controls
  - Electric door mirrors
  - Front electric windows
  - Rear headrests
  - Drivers airbag
  - Traction control
  - Alloy wheels
- Navigation system
  - Audio remote control
  - Air conditioning
  - Front head restraints
  - Metallic Paint
  - Isofix child seat anchor points
  - Central locking
- PAS
  - Digital radio
  - Climate control
  - Height adjustable drivers seat
  - 3x3 point rear seat belts
  - Passenger airbag
  - Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Dented  
Over 2 UpTo 10mm

No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Dented  
2 Or Less UpTo 10mm



8: Door nsr  
Chipped  
1 To 5

No Image



9: Door nsr  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsr  
Scratched  
Over 50mm

No Image



11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image



13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

14: Boot Lid  
Chipped  
1 To 5





15: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



16: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osr  
Scratched  
Over 50mm



18: Door osr  
Poor Previous Repair  
Poor Paint



19: Door osf  
Poor Previous Repair  
Poor Paint



20: Wing osf  
Chipped  
1 To 5

No Image



21: Wing osf  
Scratched  
Over 25mm Not Thru Paint

22: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK