



VEHICLE INSPECTION REPORT

GD17SFU

Land Rover Range Rover Evoque 2.0 eD4 SE Tech 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/06/2017	Body Style	Estate	Last service miles	58,432
Year	2017	Keys	2	MOT Due	11/09/2026
Mileage	97,635 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	4		
VIN	SALVB2CN0HH253960	Last service date	21/06/2022		

Last Service - 21.06.2022 at 58432 miles (4 services)
Timing Chain Replaced 29.07.2022 @ 59239 miles

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Audio remote control
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Wing Front Arch Extension os
Broken
Replace



3: Bumper Front
Chipped
Multiple Chips




4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Wing nsf
Chipped
1 To 5



7: Wing nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Chipped
Multiple Chips



9: Door nsr
Poor Previous Repair
Poor Paint




10: Wheel nsr
Scratched
Up To 50mm




11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Dented
Between 10mm + 30mm

No Image

18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Door osf
Chipped
1 To 5

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



21: Wing osf
Scratched
Over 25mm Not Thru Paint

22: Wheel osf
Scratched
Over 50mm



23: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK