



VEHICLE INSPECTION REPORT

KT16NUW

Peugeot 308 2.0 BlueHDi 150 GT Line 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/06/2016	Keys	1	CAP Clean	£5,000.00
Year	2016	Service history	Yes	CAP Average	£4,300.00
Mileage	65,527 Miles Warranted	Service documents	Service Book	CAP Below	£3,625.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	AUTOMATIC
Colour	RED	Last service date	27/06/2022	Gears	6
VIN	VF3LJAHXWGS142693	Last service miles	51,677		
Body Style	Estate	MOT Due	04/07/2025		

Last Service: 27/06/2022 at 51677 miles. (6 services (2 main dealer)). Book & print Service light on, Electrical circuit fault message displays on dash

Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	5.0mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osr
Chipped
1 To 5




4: Bumper Rear
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Poor Previous Repair
Poor Colour



7: Qtr Panel nsr
Poor Previous Repair
Poor Colour




8: Wheel nsr
Scratched
Over 50mm



9: Door nsf
Chipped
Edge Chip



10: Wheel nsf
Scratched
Over 50mm



11: Bonnet
Poor Previous Repair
Poor Paint



12: Bumper Front
Chipped
1 To 5



13: A Post os
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK