

VEHICLE INSPECTION REPORT

HX15XGB

Toyota Prius 1.8 VVTi Plug-in 5dr CVT Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape
		V5	Present		
Details					
Reg. date	25/03/2015	Keys	2	CAP Clean	£5,825.00
Year	2015	Service history	Yes	CAP Average	£5,075.00
Mileage	110,808 Miles Warranted	Service documents	Printout	CAP Below	£4,275.00
		Number of stamps	3	Gearbox	CVT
Fuel Type	Hybrid Electric	Last service date	29/05/2019	Gears	1
Colour	WHITE	Last service miles	39,261	Doors	5
VIN	JTDKN36P203072526	MOT Due	28/04/2026		
Body Style	Hatchback	•			

Last Service: 29/05/2019 at 39261 miles. (3 main dealer services)

_	-			
	1/	r	0	c
	v		┖	-

NSF	GT RADIAL	5.0mm	
NSR	FALKEN	4.0mm	
OSF	GT RADIAL	5.0mm	
OSR	FALKEN	4.0mm	
Spare			

Features

- Bluetooth connection
- Rear wiper
- Audio remote control
- Air conditioning
 Height adjustable drivers seat
 3x3 point rear seat belts
- Passenger airbag
- · Remote central locking
- Cruise control
- Steering wheel mounted controls

 Steering wheel mounted controls

 Digital radio

 Climate control

 Rear electric windows

 Park assist

 Telephone

 Body colou

 Front electric electric windows

 Rear headr

- ABS
- Traction control
- Partial leather seat trim
- · Park assist camera
- Body coloured bumpers
- Front electric windows
 Rear headrests
- Drivers airbagTyre pressure monitor
- Alloy wheels

• PAS

- Trip computer Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos










Condition Check



Damage Photos



1: Bumper Front Scratched Over 100mm Thru Paint



2: Bonnet Chipped Multiple Chips



3: Wing osf Chipped 1 To 5



4: Wheel osf Scratched Over 50mm



5: Door osf Chipped 1 To 5

No Image

6: Door osr Scratched Over 25mm Not Thru Paint



7: Wheel osr Scratched Over 50mm

No Image

8: Qtr Panel osr Scratched Over 25mm Not Thru Paint



9: Bumper Rear Cracked UpTo 25mm



10: Boot Lid Chipped Over 5mm




11: Wheel nsr Scratched Up To 50mm



12: Door nsr Chipped 1 To 5

No Image





14: Wheel nsf Scratched Over 50mm

Interior

Carpet Condition Upholstery Condition Average **Seat Condition** Odour Average

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK