



VEHICLE INSPECTION REPORT

GY14UGA

Peugeot 308 1.6 HDi 92 Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	16/06/2014	Keys	2	CAP Clean	£1,650.00
Year	2014	Service history	Yes	CAP Average	£1,250.00
Mileage	117,183 Miles Warranted	Service documents	Service Book	CAP Below	£850.00
Fuel Type	Diesel	Number of stamps	10	Gearbox	MANUAL
Colour	GREY	Last service date	04/09/2024	Gears	5
VIN	VF3LC9HPAES113526	Last service miles	110,116		
Body Style	Estate	MOT Due	03/11/2025		

Last Service - 04.09.2024 at 110116 miles (10 main dealer services())

Tyres

NSF	HANKOOK	4.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	5.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Telephone
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Not Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
UpTo 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Dented
Over 30mm



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
1 To 5



15: Wing osf
Dented
With Paint Damage



16: Wheel osf
Scratched
Over 50mm



17: Sill ns
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK