

## VEHICLE INSPECTION REPORT

EU18UBB

### Nissan Juke 1.6 Tekna 5dr Xtronic [Bose]

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	TBC

nama  
GRADE 4

#### Details

Reg. date	16/07/2018
Year	2018
Mileage	88,544 Miles Warranted
Fuel Type	Petrol

Colour	BLUE	MOT Due	17/02/2026
VIN	SJNFBAF15U8015378	Gearbox	CVT
Body Style	Hatchback	Gears	5
Keys	2	Doors	5

#### Tyres


NSF	SUNNY	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	SUNNY	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


• Bluetooth connection	• Cruise control	• Heated front seat	• Navigation system
• Park assist camera	• PAS	• Rear wiper	• Steering wheel mounted controls
• Digital radio	• Body coloured bumpers	• Electric door mirrors	• Front fog lights
• Air conditioning	• Folding rear seats	• Front armrest	• Front electric windows
• Front head restraints	• Height adjustable drivers seat	• Rear electric windows	• Rear headrests
• Steering wheel rake adjustment	• Steering wheel reach adjustment	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag
• Side airbags	• Central locking	• Remote central locking	• Leather seat trim
• Alloy wheels			

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Chipped  
Multiple Chips




3: Wheel nsf  
Scratched  
Over 50mm




4: Wing osf  
Chipped  
1 To 5



5: Screen Front  
Chipped  
UpTo 10mm



6: Door nsf  
Dented  
Over 30mm



7: Door nsf  
Scratched  
UpTo 25mm Thru Paint



8: Door nsr  
Scratched  
Over 25mm Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



11: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
UpTo 100mm



12: Bumper Rear  
Scratched  
Up To 25mm Thru Paint




13: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



14: Wheel nsr  
Scratched  
Over 50mm



15: Door osr  
Scratched  
Over 25mm Thru Paint



16: Door osf  
Scratched  
Over 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Wing osf  
Scratched  
Over 25mm Thru Paint

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK