

VEHICLE INSPECTION REPORT

EF65RVN

Ford Transit Connect 1.6 TDCi 115ps Limited Van

Inspection	Vehicle		nama GRADE 3
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	11/12/2015	Body Style	Panel Van	Last service miles	127,629
Year	2015	Keys	1	MOT Due	10/12/2026
Mileage	138,350 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	9	Last service date	29/07/2025
VIN	WF0RXXWPGRFU08690	Last service date	29/07/2025		

£100 ADDITIONAL FEE. Last service 29/07/2025 at 127629 miles (9 services (4 main dealer). Only driver seat heater

Emr light is on

Car been scanned and detected:

Turbocharger Boost Control Position Sensor A Performance - Stuck Low

Tyres




NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Air conditioning
- Passenger airbag
- Cruise control
- Rear parking sensor
- Front electric windows
- Central locking
- Heated front seat
- Digital radio
- Metallic Paint
- Cloth seat trim
- Navigation system
- Radio/CD
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Other
N/A
N/A



5: Wing nsf
Chipped
Multiple Chips



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Roof
Dented
Over 30mm



9: Door nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Scratched
Rusted



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Tailgate
Dented
With Paint Damage



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osf
Scratched
Up To 50mm



16: Door osf
Chipped
Edge Chip



17: Panel Front
Scratched
Over 25mm Thru Paint



18: Roof
Chipped
Edge Chip



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK