

VEHICLE INSPECTION REPORT

GF22EOO

MG Mg Hs EXCLUSIVE DCT

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	30/03/2022
Year	2022
Mileage	18,374 Miles Warranted
Fuel Type	Petrol
Colour	WHITE
VIN	LSJA24U91MN164749

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	2
Last service date	07/11/2024

Last service miles	12,234
MOT Due	29/03/2026
Gearbox	SEMI AUTO
Gears	7

£90 ADDITIONAL FEE.

Last service 07/11/2024 at 12,234 miles- 2 main dealer services. Print

Tyres



NSF	MICHELIN	4.0mm
NSR	MICHELIN	3.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Dented
Over 30mm



5: Door nsf
Dented
Over 30mm



6: Door nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
Chipped
Multiple Chips

No Image

10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Dented
Over 2 UpTo 10mm



13: Door osf
Dented
Between 10mm + 30mm



14: Wing osf
Dented
Between 10mm + 30mm



15: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		