



VEHICLE INSPECTION REPORT

GY14KVB

Ford Focus 2.0T ST-2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/04/2014	Body Style	Hatchback	Last service miles	73,447
Year	2014	Keys	2	MOT Due	14/05/2026
Mileage	77,799 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	8	Doors	5
VIN	WF0KXXGCBKES25024	Last service date	12/05/2025		

£90 ADDITIONAL FEE

Last service 12/05/2025 at 73,447 miles- 8 services (3 main dealer) Book and print

Tyres


NSF	CONTINENTAL	1.0mm
NSR	HIFLY	5.0mm
OSF	CONTINENTAL	1.0mm
OSR	HIFLY	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
Multiple Chips




4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Dented
Over 30mm



6: Door nsf
Chipped
Edge Chip



7: Aperture Seal nsr
Broken
Replace



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
Over 30mm



10: Wheel osr
Scratched
Up To 50mm



11: Qtr Panel nsr
Scratched
Up To 25mm Thru Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
Edge Chip



16: Door osf
Scratched
UpTo 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK