



# VEHICLE INSPECTION REPORT

**KP71EXE**

## Land Rover Range Rover Evoque 2.0 D200 R-Dynamic HSE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	16/09/2021	Keys	2	CAP Clean	£25,850.00
Year	2021	Service history	Yes	CAP Average	£24,550.00
Mileage	17,208 Miles Warranted	Service documents	Printout	CAP Below	£23,200.00
Fuel Type	Diesel	Number of stamps	1	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	04/09/2023	Gears	9
VIN	SALZA2ANXMH161286	Last service miles	13,859		
Body Style	Estate	MOT Due	15/09/2025		

£65 ADDITIONAL FEE. Last Service: 04/09/2023 at 13859 miles. (1 main dealer service)

### Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Digital radio
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Audio remote control
- Electric door mirrors
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Auxiliary input socket
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips





3: Door nsf  
Chipped  
1 To 5

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

No Image

5: Door nsr  
Scratched  
Over 25mm Not Thru Paint

No Image

6: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



7: Door osf  
Chipped  
1 To 5

No Image

8: Wing osf  
Scratched  
Over 25mm Not Thru Paint

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK