



VEHICLE INSPECTION REPORT

AY68ULA

Land Rover Range Rover Velar 2.0 P300 R-Dynamic SE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	17/10/2018	Body Style	Estate	Last service miles	6
Year	2018	Keys	2	MOT Due	17/10/2026
Mileage	71,796 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	8
Colour	BLACK	Number of stamps	6		
VIN	SALYA2AXXKA785558	Last service date	22/05/2025		

Last service 22/05/2025 at 67662 miles (6 main dealer services). EML light is on car has been plugged in and detects
Camshaft position sensor b circuit range performance bank 1

Tyres

NSF	KUMHO	6.0mm
NSR	KUMHO	6.0mm
OSF	KUMHO	6.0mm
OSR	KUMHO	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Chipped
Edge Chip



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Door osr
Poor Previous Repair
Poor Paint



10: Door osf
Chipped
Edge Chip



11: Wing osf
Poor Previous Repair
Poor Paint



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		