



# VEHICLE INSPECTION REPORT

**AO11LHL**

## Mercedes-Benz B-Class B200 CDI SE

nama  
 GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	30/03/2011	Colour	SILVER	Service history	None
Year	2011	VIN	WDD2452082J708230	MOT Due	22/11/2026
Mileage	111,085 Miles Warranted	Body Style	MPV	Gearbox	CVT
Fuel Type	Diesel	Keys	2	Gears	1

No service history EML light is on car has been plugged in and detects  
 Glow plug control  
 nsf window fault

### Tyres

NSF	YOKOHAMA	2.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Cracked  
Over 25mm



2: Bonnet  
Chipped  
Multiple Chips



3: Screen Front  
Cracked  
Replace



4: A Post os  
Chipped  
1 To 5



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Chipped  
1 To 5



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsf  
Dented  
Over 30mm



9: Door nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Up To 50mm



11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



12: Qtr Panel nsr  
Dented  
2 Or Less Up To 10mm



13: Bumper Rear  
Dented  
With Paint Damage




14: Lamp osr  
Broken  
Replace



15: Qtr Panel osr  
Scratched  
Rusted



16: Wheel osr  
Scratched  
Up To 50mm



17: Door osr  
Scratched  
Up To 25mm Thru Paint



18: Door osf  
Scratched  
Up To 25mm Thru Paint



19: Sill Panel Trim os  
Scratched (Painted)  
Over 25mm Thru Paint



20: Wheel osf  
Scratched  
Up To 50mm



21: Wing osf  
Chipped  
1 To 5

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
		Steering	OK