



VEHICLE INSPECTION REPORT

GY65RSZ

Nissan Juke 1.6 N-Connecta 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	08/12/2015	Body Style	Hatchback	Last service miles	41,588
Year	2015	Keys	2	MOT Due	09/01/2027
Mileage	102,866 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	3	Doors	5
VIN	SJNFBAF15U7173907	Last service date	11/01/2019		

Last Service - 11.01.2019 at 41588 miles (3 main dealer services) Gearbox fault while putting into gear
 Power steering fault

Tyres

NSF	RAPID	2.0mm
NSR	BUDGET	3.0mm
OSF	RAPID	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
UpTo 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint




8: Door nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Chipped
1 To 5




11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Roof
Dented
Over 30mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Dented
Over 2 UpTo 10mm




16: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



17: Wheel osr
Scratched
Over 50mm



18: Door osf
Dented
Over 2 UpTo 10mm



19: Door osr
Scratched
Over 25mm Not Thru Paint




20: Door osf
Poor Previous Repair
Poor Paint



21: Wing of
Dented
Between 10mm + 30mm



22: Wheel of
Scratched
Over 50mm



23: Screen Front
Chipped
Up To 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	Fault