



VEHICLE INSPECTION REPORT

HW70UZL

Ford Ranger Pick Up Double Cab Wildtrak 2.0 EcoBlue 213 Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

nama
GRADE
3

Details

Reg. date	15/12/2020	Body Style	Pick-up	Last service miles	53,001
Year	2020	Keys	2	MOT Due	09/09/2026
Mileage	53,498 Miles Not Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	1
Colour	WHITE	Number of stamps	1		
VIN	6FPPXXMJ2PLY39989	Last service date	06/08/2025		

Last Service - 06.08.2025 at 53001 miles (1 services)
 Wet Belt Replaced 06.08.2025 @ 53001 miles
 Secondhand Engine and new turbo and feed pipes fitted 14.03.2025
 EML
 NO V5

Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Air conditioning
- Drivers airbag
- Cruise control
- Park assist camera
- Front electric windows
- Passenger airbag
- Front parking sensor
- Rear parking sensor
- Rear electric windows
- Central locking
- Heated front seat
- Digital radio
- Metallic Paint
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



2: Bumper Front
Dented
Over 30mm



3: Bonnet
Chipped
1 To 5



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 30mm



7: Door nsr
Chipped
1 To 5



8: Qtr Panel nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Boot Lid
Dented
Over 30mm




11: Qtr Panel osr
Dented
Over 30mm



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
Over 2 UpTo 10mm



14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Sill Panel Trim os
Broken
Replace



16: Door osf
Dented
Over 30mm



17: Roof
Dented
Over 30mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK