



VEHICLE INSPECTION REPORT

LK64ZTX

Peugeot 3008 2.0 HDi 163 Allure 5dr Auto

Inspection

Vehicle

nama

GRADE
4

VAT	Margin
V5	Present

Details

Reg. date	19/09/2014	Body Style	Hatchback	Last service miles	37,450
Year	2014	Keys	2	MOT Due	30/07/2026
Mileage	161,343 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	1	Doors	5
VIN	VF30URHHAES110182	Last service date	29/05/2019		

£100 ADDITIONAL FEE. Last service 29/05/2019 at 37450 miles (1 main dealer service). Parking assistance system faulty message displayed
Radio faulty
Roof not working

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm


Spare

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Partial leather seat trim
- PAS
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Audio remote control
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Curtain airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Boot Lid
Dented
Over 30mm



2: Bumper Rear
Poor Previous Repair
Poor Paint




3: Qtr Panel osr
Poor Previous Repair
Poor Paint



4: Wheel osr
Scratched
Over 50mm



5: Door osr
Chipped
1 To 5



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Door osf
Poor Previous Repair
Poor Paint



8: Sill Panel Trim os
Broken
Replace



9: Wing osf
Chipped
1 To 5



10: Wheel osf
Scratched
Over 50mm



11: Bumper Front
Poor Previous Repair
Poor Colour



12: Bonnet
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm



14: Wing nsf
Chipped
1 To 5

No Image



15: Wing nsf
Scratched
Over 25mm Not Thru Paint

16: Door nsf
Chipped
1 To 5

No Image



17: Door nsf
Scratched
Over 25mm Not Thru Paint

18: Door nsr
Poor Previous Repair
Poor Paint



19: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



20: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	Fault
Windows	OK	Steering	OK