



VEHICLE INSPECTION REPORT

GV15BPX

Toyota Yaris 1.33 VVT-i Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	30/06/2015	Body Style	Hatchback	Last service miles	42,417
Year	2015	Keys	2	MOT Due	29/06/2026
Mileage	53,820 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	9	Doors	5
VIN	VNKKJ3D330A286441	Last service date	17/06/2024		

Last Service - 17.06.2024 at 42417 miles (9 services)

Tyres

NSF	TOYO	3.0mm
NSR	BUDGET	2.0mm
OSF	TOYO	3.0mm
OSR	CONTINENTAL	2.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Remote central locking
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Traction control
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Dented
Over 30mm




4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Poor Previous Repair
Poor Paint



6: Door nsr
Poor Previous Repair
Poor Paint



7: Qtr Panel nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Boot Lid
Poor Previous Repair
Poor Paint



11: Qtr Panel osr
Poor Previous Repair
Poor Paint



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Poor Previous Repair
Poor Paint



14: Door osf
Poor Previous Repair
Poor Paint



15: Wing of
Poor Previous Repair
Poor Paint



16: Wheel of
Scratched
Over 50mm



17: Screen Front
Chipped
Up To 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK